

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080123-7

RECEIVED FROM

DATE REC'D 1-26-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT

DRAWING

DWG. DASH OR

DWG.

LOT

CLASS

OPER

BUY OUT

ACCT. OR

W.O. NO.

S.O. NO.

CHARGE TO
QUANTITY
RECEIVED

322

000000

22061

0

0

00

00

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

1

732659 COVER

SHIP MEMO 35900

RECEIVED
BY
HMC-1069INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11058

RECEIVED FROM

Plant #9

DATE REC'D 1/28-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT

DRAWING

DWG. DASH OR

DWG.

LOT

CLASS

OPER

BUY OUT

ACCT. OR

W.O. NO.

S.O. NO.

CHARGE TO
QUANTITY
RECEIVED

322

000000

22052

0

0

00

00

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

3

73831-1 22052 Bearing Retainer

Ship #35857

TC Superspeed 51102

3

RECEIVED
BY
HMC-1069INSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080123-7